

(continued on page 2)

GIBBES HOUSE
Index To Photographs
HABS No. SC-445 (page 2)

- SC-445-16 SOUTHEAST ROOM, FIRST FLOOR. NOTE CORNICE, TRIM,
MANTLE AND DOOR PEDIMENTS
- SC-445-17 SOUTHEAST ROOM, FIRST FLOOR: MANTLE DETAIL (ca. 1929
addition)
- SC-445-18 SOUTHEAST ROOM, FIRST FLOOR: DOOR AND CORNICE (ca. 1929
addition). WAINSCOT, CAP AND BASE PROBABLY ORIGINAL. LOOKING
THRU HALL TO SOUTHWEST ROOM
- SC-445-19 SOUTHWEST ROOM, FIRST FLOOR, NORTH WALL. NOTE TRIM AND
MANTLE
- SC-445-20 SOUTHWEST ROOM, FIRST FLOOR: MANTLE AND OVERMANTLE PANEL
MOLD (ca. 1800)
- SC-445-21 SOUTHWEST ROOM, FIRST FLOOR: CORNICE (ca. 1772) AND
PANEL MOLD (ca. 1800)
- SC-445-22 NORTHEAST ROOM, FIRST FLOOR, SOUTH WALL. NOTE TRIM AND
MANTLE
- SC-445-23 NORTHEAST ROOM, FIRST FLOOR, SOUTH WALL: DETAIL OF MANTLE
- SC-445-24 NORTHEAST ROOM, FIRST FLOOR: MANTLE DETAIL. This mantle
was installed ca. 1929 and is said to have come from
18 Bull Street, where it was not original
- SC-445-25 NORTHWEST ROOM, FIRST FLOOR, SOUTH WALL. NOTE TRIM AND
MANTLE
- SC-445-26 NORTHWEST ROOM, FIRST FLOOR: MANTLE DETAIL. This mantle
was installed ca. 1929 and is said to have come from 18 Bull
Street, where it was not original
- SC-445-27 NORTHWEST ROOM, FIRST FLOOR: CORNICE DETAIL (original to
house, ca. 1772)
- SC-445-28 SOUTH ELEVATION, FIRST FLOOR WINDOW